

# Manhole Inspection Summary

Manhole # S15E\_\_006MH

Printed On: 9/30/2009

Page 1 of 4

## Inspection

☐ Is Incomplete Rating:

Record Plat: **15E** Node: **006** Status: **Found**

Insp Date: **9/15/09 9:56 AM**

Incomplete Comments

**Can No More Access the Manhole To Take Pictures**

Crew: **ADS1**  
Inspector: **ADS1**  
Firm: **ADS**

## Location

Address: **CALVERTON ROAD**

Cross Street: **WEST FRANKLIN**

## Manhole

Type: **Inline**

Location: **Parking Lot**

Ground Conditions: **Dry**

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments

## Cover

Shape: **Circular**

Diameter: **25.** (in.) Length: (in.) Dist A/B Grade: **0** (in.)  
**75**

Type: **Sanitary**

Condition: **Sound**

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

## Frame

Offset: **2** (in.)

Condition: ☒ Sound ☐ Cracked ☐ Leaks

## Chimney / Frame Adjustment

☐ Exists Material:

☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Corbel

Material: **Brick**

☐ Parged

Type: **Concentric/Eccentric**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Barrel

Material: **Brick**

☐ Parged

Shape: **Circular** Diameter: **48** (in.) Length: (in.)

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

## Bench

☒ Exists Material: **Brick**

☐ Parged

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

## Channel

Material: **Brick**

☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

## Steps

Count: **4** Missing: **2** ☒ **Corroded**

## Surcharge

☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

## Manhole Inspection Summary

Manhole # S15E\_\_006MH

Printed On: 9/30/2009

Page 2 of 4

## Manhole Inspection Summary

Manhole # S15E\_\_006MH

Printed On: 9/30/2009

Page 3 of 4

### 10 in. Circular Gravity Sewer

12 O'Clock Outflow

Pipe Height: (in.) Direct

Pipe Material: **PVC** ☐ Pipe Lined

Invert Depth: **9.24** (ft.) Flow Characteristics: **Slow**

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

### 10 in. Circular Gravity Sewer

6 O'Clock Inflow

Pipe Height: (in.) Direct

Pipe Material: **PVC** ☐ Pipe Lined

Invert Depth: **9.10** (ft.) Flow Characteristics: **Slow**

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

Manhole Inspection Summary

Manhole # S15E\_\_006MH

Printed On: 9/30/2009

Page 4 of 4

10 in. Circular Gravity Sewer

9 O'Clock Inflow

Pipe Height: (in.) Direct

Pipe Material: PVC ☐ Pipe Lined

Invert Depth: 8.70 (ft.) Flow Characteristics: Slow

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ Debris ☐ Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: None Pipe Seal Cond: Sound

Drop: None

Connects To: Manhole

☐ Possible Illicit Connection